



NOTES:


- | | |
|------|---|
| (01) | EXISTING ALUMINUM DOOR & FRAME TO BE REMOVED |
| (02) | EXISTING TIMBER WINDOWS & FRAMES REMOVED
existing timber windows and frames removed and opening increased in preparation for new windows |
| (03) | FORM WINDOW OPENING
existing blocked off night safe deposit box wall altered for new window opening |
| (04) | ATM OPENING BLOCKED OFF
previous ATM opening blocked off to be removed in preparation for new windows |




existing shopfront side elevation c/c -
QUEENS AVENUE




existing shopfront front elevation b'b -
MUSWELL HILL ROUNDABOUT



existing shopfront side elevation a'a -
MUSWELL HILL BOARDWAY



existing ground floor plan
1:200



All dimensions to be confirmed on site by Contractor.
Structural works to be confirmed by Structural Engineer.
All elements to comply with statutory requirements.

Copyright Tanner Design Limited,
 Marcar House 13 Parkshot Richmond Surrey TW9 2RG
 tel. 07974 324216 email. studio@tannerdesign.co.uk
www.tannerdesign.co.uk

TANNER

OLIVER BONAS

LOCATION
Muswell Hill
223 Muswell Hill Broadway, N10 1DD

DRAWING No.
TD23/OB16/EX01.1

TITLE

existing shopfront elevations

REVISION	DATE	SCALE @ A3
.	19.04.23	1:100

REVISIONS