



Left: Front elevation of 64 North Hill with current listed casement windows.

Below: 64 (left) and 62 (right) form a group listing



Photographs showing existing front elevations of 64 & 62 North Hill

Below right: Number 86 North Hill - a nearby Georgian property which has windows similar to the proposed replacement windows.



Condition of current casement windows:

Below: Poor condition - splitting, showing signs of damp and rot caused by condensetion



Date: 26/4/2023 Reference: PP-12094637

64 North Hill, N6 4RH