



Crack Monitoring

Our Ref: SI-532509 Date of Issue: 03/05/2023

Provider Details

CET - 0116 260 5309

Monitoring Details

Instruction Date:	05/10/2022	Visit Frequency (Wks)	8
Number of visits:	6		

Client Details

Insurance Company:	Direct Line 4 Business
Client Reference:	9646201
Building Consultant:	Matt Deller
Building Consultant Telephone:	07766 511187
Building Consultant Email:	
Claims Technician:	Hugh Palmer
Claims Technician Telephone:	01622 608831
Claims Technician Email:	

Risk Address

Occupier:	Mr Bisibor
Address:	150 Crouch Hill
Address:	
Town:	
County:	London
Post Code:	N8 9DX

Our Ref	Client Ref	Client Name	Issue Date
SI-532509	9646201	Sedgwick	03/05/2023

Additional instructions/notes

Stud locations

1	Ext LHS of front door
2	EXT LHS ABOVE FRONT DOOR
3	EX above drain pipe
4	EXT LHS WINDOW
5	
6	

Crack Monitoring - Readings

Studs nos.	Alignment	Visit Date	10/10/22	Visit Date	30/11/22	Visit Date	23/01/23	Visit Date	07/03/23	Visit Date	03/05/23	Visit Date	
		Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w
1	H	72.21	7.67	72.46	8.6	72.62	8.28	72.75	8.12	72.6	8.75		
2	H	67.8	5.57	68.48	6.57	68.53	6.93	68.62	6.42	68.55	6.83		
3	H	79.03	5.57	78.22	4.82	77.88	6.09	78.17	5.53	78	5.41		
3	V	102.62	5.91	101.28	6.25	101.59		101.69	6.29	101.54	6.23		
3	Check	66.8		67.77		66.84		66.76		66.77			
4	H	60.42		60.27	1.31	60.24	0.87	60.41	2.11	60.39	2.08		
Callipers:		9171		2032		2032		9085		9083			
Technician:		B.A		J.Y		J.Y		J.Y		B.A			



Giving our all

Our Ref

SI-532509

Client Ref

9646201

Client Name

Sedgwick

Issue Date

03/05/2023

Crack Monitoring - Movement Against Time

