

# PROTECTED TREE REPORT (TREE WORKS)

Haringey Council, L4, Alexandra House, Station Road, N22 7TY

|                    |                                                                                                                              |
|--------------------|------------------------------------------------------------------------------------------------------------------------------|
| Application number | HGY/2023/1127                                                                                                                |
| Application type   | Conservation Area Notification                                                                                               |
| Site Address:      | 3 Hatherley Gardens, Hornsey, London, N8 9JH                                                                                 |
| Proposal           | T10 Mimosa Fell and treat stump with eco plugs as implicated as causing subsidence damage to 150 Crouch Hill, London N8 9DX. |

|                  |              |                                |
|------------------|--------------|--------------------------------|
| RECOMMENDATION:  | No Objection |                                |
| Application date | 25/04/2023   |                                |
| Tree Inspector   | DM           | Date: 8 <sup>th</sup> May 2023 |

## **Site**

The third party Mimosa tree T10, as marked on the plan and seen in the photograph, is situated in the rear garden of the property. It is not publicly visible from street level.

A site visit was deemed necessary to determine the appropriateness of the proposed works (31/05/2023 at 13:30 approximately).

The location is also within the Crouch End Conservation Area. This protects every tree with a diameter at breast height (taken at 1.5m) >75mm.

## **Proposal**

Tree works proposed:

T10 Mimosa Fell and treat stump with eco plugs as implicated as causing subsidence damage to 150 Crouch Hill, London N8 9DX.

## **Issues**

I hold no objections to the removal of the Mimosa tree. The tree is implicated in a subsidence case.

This report should also be reference with HGY/2023/1128 (a neighbouring Sycamore tree also linked with indirect damage)

Leguminosae live roots have been found to a depth of 2.1m. Foundation depth is 960mm.

The Mimosa tree is 0.8m from the structure.

The tree also scores low when using a methodology to rate its worthiness for a Tree Preservation Order (TPO).

## **Recommendation**

**No Objection**