

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Cloudy	Date and Time:	13/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	S13		
General Description of Material:			
Wet Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	13/06/2022
------------	--	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Cloudy	Date and Time:	13/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	S12		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	13/06/2022
------------	--	-------	------------

Grid Validation Inspection Form				
Site: Clarendon Road Phase 3B		Job No: 6089		
Weather Conditions:	Sunny	Date and Time:	13/06/2022	
Name of Inspecting Party:	Giedrius Gudaitis			
Company:	Keltbray Remediation			
Nature of Inspection:	Validation			
Validation Grid:	R13			
General Description of Material:				
Dry Brown natural Clay				
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:				
No visual or olfactory signs of contamination				
VOC PID analysis (PPM):				
0				
Comments:				
N/A				
Photo(s):				
				
Signature:			Date:	13/06/2022

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	13/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	R12		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



13 Jun 2022 13:15:35
147 Hornsey Park Road
Greater London
England


Signature:		Date:	13/06/2022
------------	--	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	24/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	R11		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	24/06/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	14/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	Q13		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	14/06/2022
------------	--	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	14/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	Q12		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	14/06/2022
------------	--	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	23/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P13		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	23/06/2022
------------	---	-------	------------

Grid Validation Inspection Form

Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	23/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P12		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature: 	Date: 23/06/2022
--	----------------------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	23/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P11		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	23/06/2022
------------	--	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	07/07/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	S10		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	07/07/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	07/07/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	R10		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	07/07/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	07/07/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	Q10		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	07/07/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	07/07/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P10		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			
			
Signature:		Date:	07/07/2022

Grid Validation Inspection Form

Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	07/07/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	O10		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



7 Jul 2022 09:08:31
12 Warberry Road
Greater London
England

Signature: 	Date: 07/07/2022
-----------------------	----------------------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	07/07/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N10		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	07/07/2022
------------	--	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	07/07/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M10		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	07/07/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	07/07/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L14		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	07/07/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	17/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N13		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	17/06/2022
------------	---	-------	------------

Grid Validation Inspection Form

Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	17/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N13		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



17 Jun 2022 10:01:35
5 Silsoe Road
Greater London
England

Signature: 	Date: 17/06/2022
--	----------------------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	17/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N13		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	17/06/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	17/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N13		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			
 17 Jun 2022 10:27:42 1 Mary Neuner Road Greater London England			
Signature:		Date:	17/06/2022

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	17/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N12		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	17/06/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	25/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N11		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	17/06/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	17/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M12		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	25/05/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	17/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M11		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	17/06/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	17/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L12		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	17/06/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	17/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L11		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	17/06/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	17/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M14		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			
			
Signature:		Date:	17/06/2022

Grid Validation Inspection Form

Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	17/06/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K11		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature: 	Date: 17/06/2022
--	----------------------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	25/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M14		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	25/05/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	25/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M13		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	25/05/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	25/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L13		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	25/05/2022
------------	--	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	25/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K14		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	25/05/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	25/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K13		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	25/05/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	25/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J14		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	25/05/2022
------------	--	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	25/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J13		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	25/05/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	25/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J6		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	25/05/2022
------------	--	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	25/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I6		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	25/05/2022
------------	--	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	25/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	17		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	25/05/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	25/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I8		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	25/05/2022
------------	--	-------	------------

Grid Validation Inspection Form

Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	25/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I9		
General Description of Material:			
Dry Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	25/05/2022
-------------------	---	--------------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	04/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J10		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	04/05/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	04/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I10		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	04/05/2022
------------	--	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	04/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K7		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			
 4 May 2022 10:55:16 1 Mary Neuner Road Greater London England			
Signature:		Date:	04/05/2022

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	04/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K6		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	04/05/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	04/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L7		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			
			
Signature:		Date:	04/05/2022

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	04/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L8		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	04/05/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	04/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L9		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	04/05/2022
------------	--	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	04/05/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L10		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	04/05/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	27/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K8		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			
			
Signature:		Date:	27/04/2022

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	27/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K9		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			
			
Signature:		Date:	27/04/2022

Grid Validation Inspection Form

Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	27/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K10		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature: 	Date: 27/04/2022
-----------------------	----------------------------

Grid Validation Inspection Form				
Site: Clarendon Road Phase 3B		Job No: 6089		
Weather Conditions:	Sunny	Date and Time:	27/04/2022	
Name of Inspecting Party:	Giedrius Gudaitis			
Company:	Keltbray Remediation			
Nature of Inspection:	Validation			
Validation Grid:	J7			
General Description of Material:				
Brown natural Clay				
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:				
No visual or olfactory signs of contamination				
VOC PID analysis (PPM):				
0				
Comments:				
N/A				
Photo(s):				
 27 Apr 2022 10:29:29 1 Mary Neuner Road Greater London England				
Signature:			Date:	27/04/2022

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	27/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J8		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	27/04/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	27/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J9		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	27/04/2022
------------	---	-------	------------

Grid Validation Inspection Form				
Site: Clarendon Road Phase 3B		Job No: 6089		
Weather Conditions:	Sunny	Date and Time:	13/04/2022	
Name of Inspecting Party:	Giedrius Gudaitis			
Company:	Keltbray Remediation			
Nature of Inspection:	Validation			
Validation Grid:	i12			
General Description of Material:				
Brown natural Clay				
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:				
No visual or olfactory signs of contamination				
VOC PID analysis (PPM):				
0				
Comments:				
N/A				
Photo(s):				
				
Signature:			Date:	13/04/2022

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	13/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	i11		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			
			
Signature:		Date:	13/04/2022

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	13/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J12		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	13/04/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	13/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J11		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	13/04/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	13/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	H12		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	13/04/2022
------------	--	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	13/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	H11		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	13/04/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	13/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	G12		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	13/04/2022
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	13/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	G11		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	13/04/2022
------------	--	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	08/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	H13		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	08/04/2022
------------	--	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	08/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	H14		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	08/04/2022
------------	--	-------	------------

Grid Validation Inspection Form				
Site: Clarendon Road Phase 3B		Job No: 6089		
Weather Conditions:	Sunny	Date and Time:	08/04/2022	
Name of Inspecting Party:	Giedrius Gudaitis			
Company:	Keltbray Remediation			
Nature of Inspection:	Validation			
Validation Grid:	I14			
General Description of Material:				
Brown natural Clay				
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:				
No visual or olfactory signs of contamination				
VOC PID analysis (PPM):				
0				
Comments:				
N/A				
Photo(s):				
 8 Apr 2022 12:41:30 Coburg Road Greater London England				
Signature:			Date:	08/04/2022

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	08/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I13		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	08/04/2022
------------	--	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	08/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	G14		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



Signature:		Date:	08/04/2022
------------	---	-------	------------

Grid Validation Inspection Form

Site: Clarendon Road Phase 3B		Job No: 6089	
Weather Conditions:	Sunny	Date and Time:	08/04/2022
Name of Inspecting Party:	Giedrius Gudaitis		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	G13		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Comments:			
N/A			
Photo(s):			



8 Apr 2022 12:52:37
1 Mary Neuner Road
Greater London
England

Signature: 	Date: 08/04/2022
-----------------------	----------------------------