



Crack and Level Monitoring

Our Ref: SI-556252 Date of Issue: 05/05/2023

Provider Details

CET - 0116 260 5309

Monitoring Details

Instruction Date:	17/11/2022	Visit Frequency (Wks)	8
Number of visits:	8		

Client Details

Insurance Company:	Covea Insurance Plc
Client Reference:	9646135
Building Consultant:	Stephen Robertson
Building Consultant Telephone:	07385 494115
Building Consultant Email:	
Claims Technician:	Conan Sharp
Claims Technician Telephone:	01622 301008
Claims Technician Email:	

Risk Address

Occupier:	Alice Victor
Address:	Flat 10, 38 Colney Hatch Lane
Address:	
Town:	
County:	LONDON
Post Code:	N10 1DU



Crack and Level Monitoring - Visit Notes

Our Ref: SI-556252 **Date of Issue:** 05/05/2023

Visit Date **Note**

23/02/2023	PH did not open the door for us to take crack readings
------------	--


Crack and Level Monitoring - Site Sketch

Our Ref:

SI-556252

Date of Issue:

05/05/2023



Level Monitoring - Movement (In Millimetres) With Point TBM 1 As Relative Point for Flat 10

Our Ref: SI-556252

Date of Issue: 05/05/23

Reading date / Level Point	05/12/22	23/02/23	05/05/23
TBM 1	0	0	0
2	0	0.1	0.2
3	0	-1.3	-1.2
4	0	-0.7	-2.1

Level Monitoring - Movement (In Millimetres) With Point TBM 1 As Relative Point for Flat 2

Our Ref: SI-556252


Date of Issue: 05/05/23

Reading date / Level Point	05/12/22	23/02/23	05/05/23
TBM 5	0	0	0
6	0	0	-1.6
7	0	0	-1.5
8	0	0	-1.1

Level Monitoring - Movement (In Millimetres) With Point TBM 1 As Relative Point for Flat 10

Our Ref: SI-556252


Date of Issue: 05/05/23



Level Monitoring - Movement (In Millimetres) With Point TBM 1 As Relative Point for Flat 2

Our Ref: SI-556252

Date of Issue: 05/05/23



Our Ref	Client Ref	Client Name	Issue Date
SI-556252	9646135	Sedgwick	05/05/2023

Additional instructions/notes

Stud locations

1	Flat 2 int next to toilet door
2	Int flat 2 inside toilet..
3	Int flat 2 RHS next to steps..
4	
5	
6	

Crack Monitoring - Readings

Studs nos.	Alignment	Visit Date	05/12/22	Visit Date	08/02/23	Visit Date	05/05/23	Visit Date		Visit Date		Visit Date	
		Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w	Reading	Current c/w
1	H	74.37	8.23	72.6	6.03	71.52	5.33						
1	D	97.53	7.21	96.04	5.3	95.13	5.54						
1	Check	66.12		66.59		65.87							
2	H	59.54		57.91		56.76							
3	H	98.33	1.22	98.06	0.91	98.09	1						
Callipers:		9171		2032		6878							
Technician:		B.A		J.Y		J.Y							



Giving our all

Our Ref

SI-556252

Client Ref

9646135

Client Name

Sedgwick

Issue Date

05/05/2023

Crack Monitoring - Movement Against Time

