

Muswell Hill Library – tree works

Works are required to the trees to the rear of the Library to support the refurbishment works being undertaken. The purpose of the refurbishment is to provide compliant, accessible access into and around the library. Works include a new glazed side entrance, providing a lift from the pavement level up to the ground and first floor and the installation of accessible WCs on both floors.




Figure 1: Site plan with tree references.



Figure 2: Photo of tree T1 and T2 at rear of library – to be removed.



Figure 3 / 4: Photo of tress T1 and T2 at rear of library




Figure 5: Photo of tree T3 and T4 at rear of library – to be pruned on car park side to allow crane to be used safely.



Figure 6: Photo of tree T3 and T4.