

LEVEL MONITORING

for Subsidence Management Services

44 Lancaster Road, London, N4 4PR

Client:	Subsidence Management Services
Client Contact:	Ian Domigan
Claim Number:	4502141380
Client Reference:	IFS-AVI-SUB-22-0104436
Policy Holder:	Ms Rachel Palin
Report Date:	11 July 2023
Our Ref:	M19938



Level Monitoring Readings

The following table shows the reading levels of the various Level Monitoring Station points.

Date	1	2	3	4	5	6	7	8
25/11/2022	10.4470	10.4586	10.9110	10.8759	10.8742	10.8934	10.2273	10.3300
13/01/2023	10.4470	10.4586	10.9110	10.8759	10.8742	10.8934	10.2273	10.3300
21/02/2023	10.4463	10.4578	10.9114	10.8724	10.8754	10.8936	10.2259	10.3296
18/04/2023	10.4468	10.4590	10.9119	10.8735	10.8768	10.8946	10.2271	10.3305
10/07/2023	10.4459	10.4582		10.8651	10.8710	10.8924	10.2266	10.3307



Level Monitoring Difference Graphs

The following graphs display the progressive movement that each Level Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.



Level Monitoring Displacement Map

The following image shows an isometric representation of the movement of the property, based on the Level Monitoring Stations that were installed.



FRONT

Site Visit Notes

TBM in road in front of property, assumed value of 10.0000. Advise if DD is required.

Site Visit: 10 July 2023

No access to point 3