



Inspection Services (U.K.) Limited

The Old Church, 31 Rochester Road, Aylesford, Kent ME20 7PR

Tel: (01622) 715353

Email: enquiries@safeinspect.co.uk www.safeinspect.co.uk

Health and Safety at Work etc. Act 1974
The Lifting Operations and Lifting Equipment Regulations 1998

REPORT OF THOROUGH EXAMINATION OF LIFTING MACHINE

Contract No.	: 21353	Schedule No. :	L01	Item No. :	L008	Certificate No. :	20-22-09
						Examination Date :	25.08.23
1. Name of Client	: Redhead Demolitions Ltd						
Address of Client	: 104 Hatch Lane, Windsor, Berkshire SL4 3RW						
Situation Address	: Young's Persons Academy, Falling Lane, West Drayton, Uxbridge, UB7 7RY						
Description	: Diesel/Hydraulic Tracked Excavator. Plant N°: 9378						
Maker / Maker No.	: Komatsu PC 138US Excavator					Date of Construction :	2013
	Serial No. :		20191 KMTPC189K01020191GALEO				
2. The safe working load or loads and respective radii subject to repairs, alterations or renewals (If any)	Refer to manufacturers guidance						
3. Defects found which affect safety and repairs required to be carried out							
(a) Immediately	None						
(b) Within a specified time	None						
4. Other necessary repairs required to enable the machine to be used safely	None						
5. What parts (If any) were inaccessible	Enclosed Mechanical and Electrical Parts & Those Beyond Vision						
6. Observations	Hours @ 4917 Rear camera working OK Horn working Hydraulic hose outer sheathing perished						

I hereby certify that the above information is correct and that the equipment has been thoroughly examined in accordance with the appropriate provisions detailed above and found to be free from any defect likely to affect safety other than those recorded in Sections 3 & 4

Signature

 I. WATSON

Certificate Issue Date : 31.08.23

Qualification

ENGINEER SURVEYOR

Previous Certificate No. : UNKNOWN

Previous Examination Date : UNKNOWN

Next Examination Due Date: 25.08.24

Certificate No. : 20-22-09

End of Report