






enamel bath placed back in the original position  
 where the shower is currently  
 -All breaches in the riser to be made good with blocks to  
 60 minutes fire integrity with a new isolation valve under  
 the bath

replacement WC ( existing is 1 year old)



replacement wallhung basin



Terratinta porcelain stoneware series LESS



To replace damaged  
 and chipped existing  
 tiles


100x100mm

<https://www.onetile.co.uk/en-uk/less-beige-10x10-8-5-matte.aspx?srsId=AfmBOoprQEIht9za23EMuztcQDuHSQPvLedel4kPI0vGTk7T0UzLVh2x5BQ>

0 0.5 1m



scale 1:20 @A3



Proposed bathroom

**CONSTANTINE ARCHITECTS**

e. [c@constantinearchitects.co.uk](mailto:c@constantinearchitects.co.uk)  
 m. 07958 455 245  
 w. [www.constantinearchitects.co.uk](http://www.constantinearchitects.co.uk)