

EN185/TT/2025/R2 – Verification Statement – Decommissioning of BH01

Figure 3. SITE PHOTOGRAPHS DURING DECOMMISSIONING OF BH01 9th February 2026

Photos taken by H Lang of Ensure Environmental Consulting Ltd 09/02/2026

Photo 1 Secure working area over BH01



Photo 2 BH01 Cover prior to lifting



Photo 3 BH01 Following removal of cover showing 2 monitoring installations




Photo 4 BH01 Final bentonite placement at top of well following backfill



Photo 5 BH01 Surface concreted and finished over bentonite seal



Photo 6 Location of WS01



Photo 7 Location of WS02 – concreted over



Photo 8 Location of WS03



Photo 9 Location of WS04 - concreted over

