




Photograph 5 – Northern area of existing wholesalers, showing metal sheet roofing



Photograph 6 – Adjoining building adjacent to warehouse in the south west of site, location of WS01



Photograph 7 – Inside storage area in the south west of site



Photograph 8 – Double concrete slab encountered in WS01 to 0.43m begl.