

LEVEL MONITORING

for SMS (AVI, PRE)

123 Morley Avenue, London, N22 6NP

Client:	SMS (AVI, PRE)
Client Contact:	Refer to iSubs
Claim Number:	4503989697
Client Reference:	IFS-AVI-SUB-25-0123514
Policy Holder:	Miss Sulmah Azmutally
Report Date:	9 July 2026
Our Ref:	M27362



Level Monitoring Readings

The following table shows the reading levels of the various Level Monitoring Station points.

Date	1	2	3	4	5	6	7
16/06/2026	10.0000	9.9307	9.9606	9.9566	10.0107	10.0203	9.8725
07/07/2026	10.0000	9.9307	9.9609	9.9551	10.0077	10.0180	9.8696



Level Monitoring Difference Graphs

The following graphs display the progressive movement that each Level Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.



Level Monitoring Displacement Map

The following image shows an isometric representation of the movement of the property, based on the Level Monitoring Stations that were installed.



FRONT

Site Visit Notes

TBM 1 is assumed to be measuring at 10.0000m.

Site Visit: 16 June 2026

TBM 1 point 1 requires access through the house.