

LEVEL MONITORING

for SMS (AXA)

15 Meads Road, London, N22 6RN

Client:	SMS (AXA)
Client Contact:	Refer to iSubs
Claim Number:	450-098-9844
Client Reference:	IFS-AXA-SUB-25-0125791
Policy Holder:	Mrs Eleni Kyriacou
Report Date:	2 July 2026
Our Ref:	M26350


Level Monitoring Readings

The following table shows the reading levels of the various Level Monitoring Station points.

Date	1	2	3	4	5
21/01/2026	10.0000	10.0055	9.8314	9.7163	9.7207
17/03/2026	10.0000	10.0065	9.8332	9.7169	9.7209
07/05/2026	10.0000	10.0058	9.8320	9.7155	9.7195
30/06/2026	10.0000	10.0065	9.8314	9.7133	9.7191



Level Monitoring Difference Graphs

The following graphs display the progressive movement that each Level Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.



Level Monitoring Displacement Map

The following image shows an isometric representation of the movement of the property, based on the Level Monitoring Stations that were installed.



FRONT

Site Visit Notes

TBM is on point 1, it has an assumed value of 10.0000m. TBM 2 is a manhole in the road to front right of property. If this is not suitable, please advise if a deep datum is required.