



Northern wall test areas



N1 - Chimneybreast corner trial area to northern wall with extensive damage. Almost all the brick faces are coming away. Bricks remain stable, but render removal over corner is more difficult and thin pier is venerable. Render to remain in place.



N4 - Chimney back trial area to northern wall with extensive damage. Brick faces are coming away bricks are crumbling with large chunks falling away. Render to remain in place over chimneybreasts.



N5 - Trial areas to northern wall with varying damage. Upper render removes more easily with little damage to brick. At lower levels more damage is present with brick faces coming away, but the bricks remain stable. Render removal to continue carefully. Where removal causes more extensive damage localised areas of render will be retained

GENERAL NOTES
1. Drawings to be read in conjunction with all other Architect's information, specifications and information from Structural Engineer and other Consultants.
2. All operatives onsite to be aware of house Listing status and all original features throughout entire house to be protected/untouched throughout building works. Contractor responsible for care and protection of all listed elements throughout building works.
3. All work to comply with current Building Regulations.
4. Contractor to check all site dimensions prior to commencement to installation onsite and not to scale from this drawing unless scale bar provided.
5. Contractor to refer all discrepancies to Architect.
6. Copyright: All rights reserved. This drawing must not be reproduced without permission.

REV.	DATE	DESCRIPTION	CHK

NOTES

RETROUVIUS

2A Ravensworth Road | London
NW10 5NR | +44(0)20 8960 8676
projectenquires@retrovius.com

Project no: 192
Project name: SOUTHWOOD LANE
Drawing title: Lower Ground Floor Render Strip Out
Photos 2
Drawing no: 192-DET-203
Date: 07/08/2026

Rev: First Issue
Drawn by: GF Checked by: JF