

Monitoring Details

Provider Name:	My Home Needs Ltd	Monitoring Interval:	8 Weekly
Instruction Date:	14/12/2022	Number of Visits:	4
Reading Date:	05/10/2023	Visits Completed:	4
Date of Issue:	05/10/2023	Visits Outstanding:	0

Client Details

Client:	Davies
Job Reference:	72228824

Monitored Address

Occupier:	
Address:	133 Morley Avenue, London, N22 6NP
Telephone:	Email:

Locations Monitored

- Set 1:** Internal. Kitchen left wall adjacent to extractor
- Set 2:** Internal. Kitchen RH wall inside return
- Set 3:** Internal. Kitchen RH wall adjacent to boiler next to back door
- Set 4:** Internal. Kitchen RH wall high level


Crack Readings (Displayed in millimetres) - Kitchen left wall adjacent to extractor

Visits	1 = 2 H
03/01/2023	88.27
07/03/2023	88.35
25/04/2023	88.35
05/10/2023	88.46

Crack Reading Differences (Displayed in millimetres)

Visits	1 = 2 H
03/01/2023	N/A
07/03/2023	0.08 ↑
25/04/2023	0.00 =
05/10/2023	0.11 ↑

Crack Reading Chart




Crack Readings (Displayed in millimetres) - Kitchen RH wall inside return

Visits	3 = 4 H	3 = 5 V	4 = 5 DC
03/01/2023	57.16	62.82	81.36
07/03/2023	57.86	62.91	81.31
25/04/2023	57.75	62.91	81.39
05/10/2023	57.84	62.89	81.41

Crack Reading Differences (Displayed in millimetres)

Visits	3 = 4 H	3 = 5 V	4 = 5 DC
03/01/2023	N/A	N/A	N/A
07/03/2023	0.70 ↑	0.09 ↑	-0.05 ↓
25/04/2023	-0.11 ↓	0.00 =	0.08 ↑
05/10/2023	0.09 ↑	-0.02 ↓	0.02 ↑

Crack Reading Chart



Kitchen RH wall inside return (Pair Three): LJ


Crack Readings (Displayed in millimetres) - Kitchen RH wall adjacent to boiler next to back door

Visits	6 = 7 H	7 = 8 V	6 = 8 DC
03/01/2023	88.16	84.24	132.25
07/03/2023	88.18	84.15	132.30
25/04/2023	88.17	84.18	132.27
05/10/2023	88.31	84.14	132.32

Crack Reading Differences (Displayed in millimetres)

Visits	6 = 7 H	7 = 8 V	6 = 8 DC
03/01/2023	N/A	N/A	N/A
07/03/2023	0.02 ↑	-0.09 ↓	0.05 ↑
25/04/2023	-0.01 ↓	0.03 ↑	-0.03 ↓
05/10/2023	0.14 ↑	-0.04 ↓	0.05 ↑

Crack Reading Chart




Crack Readings (Displayed in millimetres) - Kitchen RH wall high level

Visits	9 = 10 H
03/01/2023	99.81
07/03/2023	99.88
25/04/2023	99.67
05/10/2023	100.00

Crack Reading Differences (Displayed in millimetres)

Visits	9 = 10 H
03/01/2023	N/A
07/03/2023	0.07 ↑
25/04/2023	-0.21 ↓
05/10/2023	0.33 ↑

Crack Reading Chart



Homeowner Notes

Visit	Homeowner Notes
03/01/2023	No concerns raised.
07/03/2023	No concerns raised.
25/04/2023	No concerns raised.
05/10/2023	No concerns raised.