

Monitoring Details:

Level Monitoring

Provider Name: My Home Needs

Monitoring Interval: Every 6 weeks

Instruction Date: 27/06/2023

Number of Visits: 50

Reading Date:

Visits Completed: 2

Date of Issue: 17/01/2024

Visits Outstanding: 48

Client Details:

Client: Questgates

Engineer / Handler: -

Job Reference:

Monitored Address:

Occupier: Georgina Herskovits

Address: 2 Ringwood Avenue, ,, London, N2 9NS


~~Telephone:~~

Email: -

Front Elevation



Site Plan




Level Readings

	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	17/07/23	05/10/23	16/01/24					
1	10.7362	10.7352	10.7399					
2	10.7388	10.7368	10.7422					
3	10.8369	10.8356	10.8374					
4	10.8432	10.8437	10.8434					
Taken by	N/A	N/A	T.P					
Serial number			524791					


Level Movement (Displayed in Millimeters)

	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	17/07/23	05/10/23	16/01/24					
1	0	-1	+3.8					
2	0	-2	+3.5					
3	0	-1.3	+0.6					
4	0	+0.5	+0.3					

Level Readings Chart (Points 1 - 4)



Relative Movement (Relative Survey, for illustration purposes only)



16/07/2023 04/10/2023 16/01/2024

