

Monitoring Details:

Level Monitoring

Provider Name: My Home Needs

Monitoring Interval: Every 6 weeks

Instruction Date: 27/06/2023

Number of Visits: 50

Reading Date:

Visits Completed: 4

Date of Issue: 26/02/2024

Visits Outstanding: 46

Client Details:

Client: Questgates

Engineer / Handler: -

Job Reference:

Monitored Address:

Occupier:

Address: 2 Ringwood Avenue, London, N2 9NS


Telephone:

Email: -

Front Elevation



Site Plan




Level Readings

	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	17/07/23	05/10/23	16/01/24	25/02/24				
1	10.7362	10.7352	10.7399	10.7414				
2	10.7388	10.7368	10.7422	10.7432				
3	10.8369	10.8356	10.8374	10.8380				
4	10.8432	10.8437	10.8434	10.8436				
Taken by	N/A	N/A	T.P	BJ				
Serial number			524791	523158				


Level Movement (Displayed in Millimeters)

	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	17/07/23	05/10/23	16/01/24	25/02/24				
1	0	-1	+3.8	+5.2				
2	0	-2	+3.5	+4.4				
3	0	-1.3	+0.6	+1.1				
4	0	+0.5	+0.3	+0.4				

Level Readings Chart (Points 1 - 4)



Relative Movement (Relative Survey, for illustration purposes only)



16/07/2023 04/10/2023 16/01/2024 25/02/2024

