



DETAILS OF CRACK MONITORING

GHG Reference	S2332465
Name of Insured	Mr Jonathan Leslie
Risk Address	14 Bloomfield Road, London, , United Kingdom, N6 4ET
Telephone	
Mobile	


All measurements are in mm.

LOCATION DETAILS

Location	Internal dining room
Crack Width	5.00
Alignment	Horizontal



GRAPH OF CRACK MOVEMENT



MONITORING READINGS

21/11/2023	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
	Dining room	A-B	Horizontal	62.867	0.000	0.000
		B-C	Vertical	63.667	0.000	0.000
		A-C	Diagonal	89.200	0.000	0.000
14/12/2023	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
	SML	A-B	Horizontal	63.820	0.953	0.953
		B-C	Vertical	64.153	0.487	0.487
		A-C	Diagonal	88.097	-1.103	-1.103
29/02/2024	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
		A-B	Horizontal	63.887	1.020	0.067
		B-C	Vertical	63.720	0.053	-0.433
		A-C	Diagonal	87.720	-1.480	-0.377

25/04/2024	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
SML		A-B	Horizontal	63.927	1.060	0.040
		B-C	Vertical	63.817	0.150	0.097
		A-C	Diagonal	88.060	-1.140	0.340