



# GEOSHIELD

## Verification Certificate

Date: 25 May 2023

### Landmark Brickwork Limited

**Phase 3 – Clarendon Road – Block D1, Perimeter Termination**


**Hornsey  
North London**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

**Paul Colbeck**  
Director of Site Services





## Verification Certificate

Date: 3 July 2024

**Landmark Brickwork Limited**

**Phase 3 – Clarendon Road – Block D2, Perimeter Termination**


**Hornsey  
North London**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

**Paul Colbeck**  
Director of Site Services





# GEOSHIELD

## Verification Certificate

Date: 1 February 2023

### Landmark Brickwork Limited

**Phase 3 – Clarendon Road – Block D3, Perimeter Termination**


**Hornsey  
North London**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

**Paul Colbeck**  
Director of Site Services





# GEOSHIELD

## Verification Certificate

Date: 8 August 2024

### Landmark Brickwork Limited

**Phase 3 – Clarendon Road – Block D4, Perimeter Termination**

**Hornsey  
North London**

The documentation in this handover package shows that the installation of the Gas Membrane and ancillaries was installed to specification.

Verified in accordance with BS 8485:2015+A1:2019 and CIRIA 735.

All areas were verified, and remediation issues corrected.

**Paul Colbeck**  
Director of Site Services

