

Park and footpath immediately east of the site





Large tree located in the southeast corner of the site





Church occupying the site





Church occupying the site





Area in front of the church





View north to south along eastern boundary





East facing external elevation of the church



East facing external elevation of the church






East facing external elevation of the church





View north to south along eastern boundary rear of site





In between hall and rear of the church





Damaged foundations of Hall





Large tree within southeast corner of site





Overgrown area to rear of the site





Damaged foundations associated with rear of the Hall





Rear external elevation of the Hall





Southern boundary fence





Side elevation of residential property immediately  
south of the site (No.1 Braemar Avenue)





Hall to rear of site





Area between Hall and rear of Church





View SW to NE across the site showing the church, Braemar Road, hedge and Telegraph pole





View of Hall leaning inwards





Entrance to Hall





Side elevation of residential property immediately south of the site  
(No. 1 Braemar Avenue)





Stumps immediately west of the site on Braemar Avenue





West facing elevation of church

